



WIRING DIAGRAM GS-1000

TO SW. PNL
91 T-CONN
FROM T1-1-5